

MARYLAND HISTORICAL TRUST

WA-V-018
District 4
Map 22
Parcel 46
MAGI # 2211865635

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Mt. Airy

2 LOCATION

STREET & NUMBER

Broadfording Road, N. side 1 1/2 mile W. of St. Paul's Church Rd.

CITY, TOWN

CONGRESSIONAL DISTRICT

X VICINITY OF Clear Spring 6

STATE

COUNTY

Maryland

Washington

3 CLASSIFICATION

CATEGORY

OWNERSHIP

STATUS

PRESENT USE

☐ DISTRICT

☐ PUBLIC

X ☒ OCCUPIED

X ☒ AGRICULTURE

☐ MUSEUM

X ☒ BUILDING(S)

X ☒ PRIVATE

☐ UNOCCUPIED

☐ COMMERCIAL

☐ PARK

☐ STRUCTURE

☐ BOTH

☐ WORK IN PROGRESS

☐ EDUCATIONAL

X ☒ PRIVATE RESIDENCE

☐ SITE

PUBLIC ACQUISITION

ACCESSIBLE

☐ ENTERTAINMENT

☐ RELIGIOUS

☐ OBJECT

☐ IN PROCESS

☐ YES: RESTRICTED

☐ GOVERNMENT

☐ SCIENTIFIC

☐ BEING CONSIDERED

☐ YES: UNRESTRICTED

☐ INDUSTRIAL

☐ TRANSPORTATION

X ☒ NO

☐ MILITARY

☐ OTHER:

4 OWNER OF PROPERTY

NAME

Ora Ernst

Telephone #:

STREET & NUMBER

Route #, Box 7

CITY, TOWN

STATE, zip code

Clear Spring

VICINITY OF

Maryland 21722

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE.

REGISTRY OF DEEDS, ETC.

Washington County Court House

Liber #:222

Folio #:219

STREET & NUMBER

West Washington Street

CITY, TOWN

STATE

Hagerstown

Maryland 21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION**CONDITION**

☒ EXCELLENT ☐ DETERIORATED
☐ GOOD ☐ RUINS
☐ FAIR ☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☒ ALTERED < 50%

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This farmhouse is a two story, three bay L-shaped brick structure with all stretcher bricks used at the front elevation. Segmental arches are present above the windows and doors. A one story, early 20th century porch extends across the entire front elevation. The main entrance is centrally located and includes a broad transom and sidelights. The exterior of the front part of the house is characteristic of the early 20th century. Interior woodwork in some areas is more typical of work during the third quarter of the 19th century. Also present on the property is a large frame bank barn. According to the present owner, the house was damaged heavily in a storm at the turn of the century.

CONTINUE ON SEPARATE SHEET IF NECESSARY

| PERIOD | | AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW | | | |
|---|--|--|---|--|--|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION | |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE | |
| <input type="checkbox"/> 1500-1599 | <input checked="" type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE | |
| <input type="checkbox"/> 1600-1699 | <input checked="" type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN | |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER | |
| <input checked="" type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION | |
| <input type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) | |
| | | <input type="checkbox"/> INVENTION | | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This farmhouse which appears from the exterior to date from the Ca. 1900 period is actually an older structure as evidenced by interior woodwork. This large property has for many years as a stock farm.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY 333 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Paula Stoner, Architectural Historian

ORGANIZATION

Preservation Associates

STREET & NUMBER

109 West Main Street, Box 202

CITY OR TOWN

Sharpsburg

DATE

July 1978

TELEPHONE

301-432-5466


STATE

Maryland 21782

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438





WA-IT-018

S.E.

Mt. Airy

Broadfording Road, 1 1/2 miles W. of
t. Paul's Church Road.
Clear Spring Vicinity

PAULA STONER DICKERSON
CONSULTANT, WASHINGTON, DC
HISTORIC SITES SURVEY



WA-V-018

S.

Dec. 1976

Mt. Airy

Broadfording Rd., W. of St.
Paul's Church Rd.
Clear Spring Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



WA-V-013

Barn S.W.

Dec. 1976

Mt. Airy

Broadfording Rd. W. of St.
Paul's Church Rd.
Clear Spring Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO
HISTORICAL SITES SURVEY